



End-of-Sale and End-of-Life Announcement for the Cisco Telepresence MX700D, MX800S and MX800D

EOL12745 - Amended

Cisco announces the end-of-sale and end-of-life dates for the Cisco Telepresence MX700D, MX800S and MX800D. The last day to order the affected product(s) is April 1, 2019. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

Table 1. End-of-Life Milestones and Dates for the Cisco Telepresence MX700D, MX800S and MX800D

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	October 1, 2018
End-of-Sale Date: HW	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	April 1, 2019
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	June 30, 2019
End of SW Maintenance Releases Date: HW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	March 31, 2020
End of Vulnerability/Security Support: HW	The last date that Cisco Engineering may release a planned maintenance release or scheduled software remedy for a security vulnerability issue.	March 31, 2022
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	March 31, 2020
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	March 31, 2020
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	June 27, 2023
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	March 31, 2024

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
CAB-2DC-BRL-0.6M-	DC Power Cable w/Barrel Plug, 0.6 meters long for MXCAM-D	There is currently no replacement product available for this product.	-	-
CAB-2DC-BRL-0.6M=	DC Power Cable w/Barrel Plus, 0.6 meters long for MXCAM-D	There is currently no replacement product available for this product.	-	-
CAB-2DC-BRL-1.15M-	DC Power Cable w/Barrel Plug, 1.15 meters long for MXCAM-D	There is currently no replacement product available for this product.	-	-
CAB-2DC-BRL-1.15M=	DC Power Cable w/Barrel Plus, 1.15 meters long for MXCAM-D	There is currently no replacement product available for this product.	-	-
CAB-2DC4MIN-0.65M-	4-PIN MINI DIN, 0.65 meters for MX800	There is currently no replacement product available for this product.	-	-
CAB-2DC4MIN-0.65M=	4-PIN MINI DIN, 0.65 meters for MX800	There is currently no replacement product available for this product.	-	-
CAB-2DC4MINI-0.3M-	4-PIN MINI DIN, 0.3 meters for MX700	There is currently no replacement product available for this product.	-	-
CAB-2DC4MINI-0.3M=	4-PIN MINI DIN, 0.3 meters for MX700	There is currently no replacement product available for this product.	-	-
CAB-2HDMILK-0.95M-	HDMI to HDMI Cable, 0.95 meters long for MX700	There is currently no replacement product available for this product.	-	-
CAB-2HDMILK-0.95M=	HDMI to HDMI Cable, 0.95 meters long for MX700	There is currently no replacement product available for this product.	-	-
CAB-2HDMILK-1.20M-	HDMI to HDMI Cable, 1.20 meters long for MX800	There is currently no replacement product available for this product.	-	-
CAB-2HDMILK-1.20M=	HDMI to HDMI Cable, 1.20 meters long for MX800	There is currently no replacement product available for this product.	-	-
CAB-2HDMILK-1.4M-	HDMI to HDMI Cable, 1.4 meters long for MX800	There is currently no replacement product available for this product.	-	-
CAB-2HDMILK-1.4M=	HDMI to HDMI Cable, 1.4 meters long for MX800	There is currently no replacement product available for this product.	-	-
CAB-2HDMILK-1.6M-	HDMI to HDMI Cable, 1.6 meters long for MX800	There is currently no replacement product available for this product.	-	-
CAB-2HDMILK-1.6M=	HDMI to HDMI Cable, 1.6 meters long for MX800	There is currently no replacement product available for this product.	-	-
CAB-2HDMILK-1.75M-	HDMI to HDMI Cable, 1.75 meters long for MX700	There is currently no replacement product available for this product.	-	-
CAB-2HDMILK-1.75M=	HDMI to HDMI Cable, 1.75 meters long for MX700	There is currently no replacement product available for this product.	-	-
CAB-2HDMILK-1.85M-	HDMI to HDMI Cable with Lock, 1.85 meters long for MX800	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
CAB-2HDMILK-1.85M=	HDMI to HDMI Cable, 1.85 meters long for MX800	There is currently no replacement product available for this product.	-	-
CAB-2HDMILK-2.0M-	HDMI to HDMI Cable, 2.0 meters long for MX700	There is currently no replacement product available for this product.	-	-
CAB-2HDMILK-2.0M=	HDMI to HDMI Cable, 2.0 meters long for MX700	There is currently no replacement product available for this product.	-	-
CAB-2HDMILK-2.2M-	HDMI to HDMI Cable, 2.2 meters long for MX700	There is currently no replacement product available for this product.	-	-
CAB-2HDMILK-2.2M=	HDMI to HDMI cable	There is currently no replacement product available for this product.	-	-
CAB-2HDMILK-2.75M-	HDMI to HDMI Cable, 2.75 meters long for MX800 Dual	There is currently no replacement product available for this product.	-	-
CAB-2HDMILK-2.75M=	HDMI to HDMI Cable, 2.75 meters long for MX800 Dual	There is currently no replacement product available for this product.	-	-
CAB-DIN-BRL-0.4M-	4-PIN MINI DIN to 2mm Barrel Plug, 0.4 meters for MX800	There is currently no replacement product available for this product.	-	-
CAB-DIN-BRL-0.4M=	4-PIN MINI DIN to 2mm Barrel Plug, 0.4 meters for MX800	There is currently no replacement product available for this product.	-	-
CAB-DIN-BRL-1.05M-	4-PIN MINI DIN to 2mm Barrel Plug, 1.05 meters for MX600	There is currently no replacement product available for this product.	-	-
CAB-DIN-BRL-1.05M=	4-PIN MINI DIN to 2mm Barrel Plug, 1.05 meters for MX700	There is currently no replacement product available for this product.	-	-
CAB-ETHRJ45-0.7M-	Shielded Twisted Pair Eth Cable w/ RJ45 0.7 mts, MXCAM-D	There is currently no replacement product available for this product.	-	-
CAB-ETHRJ45-0.7M=	Shielded Twisted Pair Eth Cable w/ RJ45 0.7 mts, MXCAM-D	There is currently no replacement product available for this product.	-	-
CAB-ETHRJ45-1.05M-	Shielded Twisted Pair Ethernet Cable w/ RJ45 1.05 mts	There is currently no replacement product available for this product.	-	-
CAB-ETHRJ45-1.05M=	Shielded Twisted Pair Ethernet Cable w/ RJ45 1.05 mts long,	There is currently no replacement product available for this product.	-	-
CAB-ETHRJ45-1.2M-	Shielded Twisted Pair Eth Cable w/ RJ45 1.2 mts,MXCAM-D	There is currently no replacement product available for this product.	-	-
CAB-ETHRJ45-1.2M=	Shielded Twisted Pair Eth Cable w/ RJ45 1.2 mts,MXCAM-D	There is currently no replacement product available for this product.	-	-
CAB-ETHRJ45-1.35M-	Shielded Twisted Pair Ethernet Cable w/ RJ45 1.35 m	There is currently no replacement product available for this product.	-	-
CAB-ETHRJ45-1.35M=	Shielded Twisted Pair Ethernet Cable w/ RJ45 1.3 mts	There is currently no replacement product available for this product.	-	-
CAB-ETHRJ45-1.85M-	Shielded Twisted Pair Ethernet Cable w/ RJ45 1.85 mts	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
CAB-ETHRJ45-1.85M=	Shielded Twisted Pair Ethernet Cable w/ RJ45 1.85 mts	There is currently no replacement product available for this product.	-	-
CAB-ETHRJ45-2.2M-	Shielded Twisted Pair Ethernet Cable w/ RJ45 2.2 mts long,	There is currently no replacement product available for this product.	-	-
CAB-ETHRJ45-2.2M=	Shielded Twisted Pair Ethernet Cable w/ RJ45 2.2 mts long,	There is currently no replacement product available for this product.	-	-
CAB-ETHRJ45-2.6M-	Shielded Twisted Pair Ethernet Cable w/ RJ45 2.6 mts long,	There is currently no replacement product available for this product.	-	-
CAB-ETHRJ45-2.6M=	Ethernet Cable w/ RJ45 2.6 meters	There is currently no replacement product available for this product.	-	-
CAB-ETHRJ45-3.45M-	Ethernet Cable w/ RJ45 3.45 meters	There is currently no replacement product available for this product.	-	-
CAB-ETHRJ45-3.45M=	Ethernet Cable w/ RJ45 3.45 meters	There is currently no replacement product available for this product.	-	-
CAB-ETHRJ45-4.2M-	Shielded Twisted Pair Ethernet Cable w/ RJ45 4.2 mts long,	There is currently no replacement product available for this product.	-	-
CAB-ETHRJ45-4.2M=	Shielded Twisted Pair Ethernet Cable w/ RJ45 4.2 mts long,	There is currently no replacement product available for this product.	-	-
CAB-MIC-RJ.5-0.5M-	RJ.5 Microphone Cable, 0.5 meters long, for MXCAM-D	There is currently no replacement product available for this product.	-	-
CAB-MIC-RJ.5-0.5M=	RJ.5 Microphone Cable, 0.5 meters long, for MXCAM-D	There is currently no replacement product available for this product.	-	-
CAB-MIC-RJ.5-1.0M-	RJ.5 Microphone Cable, 1.0 meters long, for MXCAM-D	There is currently no replacement product available for this product.	-	-
CAB-MIC-RJ.5-1.0M=	RJ.5 Microphone Cable, 1.0 meters long, for MXCAM-D	There is currently no replacement product available for this product.	-	-
CAB-MX700-L-SPKR-	Left Speaker Cable for MX700	There is currently no replacement product available for this product.	-	-
CAB-MX700-L-SPKR=	Left Speaker Cable for MX700	There is currently no replacement product available for this product.	-	-
CAB-MX700-R-SPKR-	Right Speaker Cable for MX700	There is currently no replacement product available for this product.	-	-
CAB-MX700-R-SPKR=	Right Speaker Cable for MX700	There is currently no replacement product available for this product.	-	-
CAB-MX800-L-SPKR-	Left Speaker Cable for MX800	There is currently no replacement product available for this product.	-	-
CAB-MX800-L-SPKR=	Left Speaker Cable for MX800	There is currently no replacement product available for this product.	-	-
CAB-MX800-R-SPKR-	Right Speaker Cable for MX800	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
CAB-MX800-R-SPKR=	Right Speaker Cable for MX800	There is currently no replacement product available for this product.	-	-
CAB-USB-A-B-1.15M-	USB A to USB B Cable, 1.15 meters long for MX700	There is currently no replacement product available for this product.	-	-
CAB-USB-A-B-1.15M=	USB A to USB B Cable, 1.15 meters long for MX700	There is currently no replacement product available for this product.	-	-
CS-MX700D-2CAM-K9	SPARK MX700D, Dual 55, Dual Cam, for SPARK subscription only	CS-ROOM55D-MSRP-K9	Cisco Webex Room 55D, Dual 55" Screens	-
CS-MX800D-2CAM-K9	SPARK MX800D, Dual 70, Dual Cam, SPARK subscription only	CS-ROOM70DG2-M-K9	Cisco Webex Room 70 Dual G2 with Touch10 for Webex Subs	-
CS-MX800S-2CAM-K9	SPARK MX800S, Single 70, Dual Cam, SPARK subscription only	CS-ROOM70SG2-M-K9	Cisco Webex Room 70 Single G2 with Touch10 for Spark Subs	-
CTS-MX700-D-CAMCV-	Dual cam top rear cover, Center Top profile and.....	There is currently no replacement product available for this product.	-	-
CTS-MX700-D-CAMCV=	Dual cam top rear cover, Center Top profile and.....	There is currently no replacement product available for this product.	-	-
CTS-MX700-D-FSK	Cisco MX700 Dual Screen Floor Stand Kit	There is currently no replacement product available for this product.	-	-
CTS-MX700-D-FSK=	Cisco MX700 Dual Screen Floor Stand Kit	There is currently no replacement product available for this product.	-	-
CTS-MX700-D-LGR-	MX700 Dual Floor Stand Lower Grill	There is currently no replacement product available for this product.	-	-
CTS-MX700-D-LGR=	MX700 Dual Floor Stand Lower Grill	There is currently no replacement product available for this product.	-	-
CTS-MX700-D-WMK	Cisco MX700 Dual Screen Wall Mount Kit - hangs on wall	There is currently no replacement product available for this product.	-	-
CTS-MX700-D-WMK=	Cisco MX700 Dual Screen Wall Mount Kit - hangs on wall	There is currently no replacement product available for this product.	-	-
CTS-MX700-DDC-TGR-	MX700 Dual - Dual Camera Top Grill	There is currently no replacement product available for this product.	-	-
CTS-MX700-DDC-TGR=	MX700 Dual Dual Camera Top Grill	There is currently no replacement product available for this product.	-	-
CTS-MX700-DSC-TGR-	MX700 Dual - Single Camera Top Grill	There is currently no replacement product available for this product.	-	-
CTS-MX700-DSC-TGR=	MX700 Dual Single Camera Top Grill	There is currently no replacement product available for this product.	-	-
CTS-MX700-DWM-LGR-	MX700 Dual Wallmount Lower Grill	There is currently no replacement product available for this product.	-	-
CTS-MX700-MON-L-D-	Left Monitor for MX700 55 Dual Screen w/Dual Camera	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
CTS-MX700-MON-L-D=	Spare Left Monitor for MX700 55 Dual Screen w/Dual Camera	There is currently no replacement product available for this product.	-	-
CTS-MX700-MON-L-S-	Left Monitor for MX700 55 Dual Screen w/ Single Camera	There is currently no replacement product available for this product.	-	-
CTS-MX700-MON-L-S=	Spare Left Monitor for MX700 55 Dual Screen w/ 1 cam	There is currently no replacement product available for this product.	-	-
CTS-MX700-MON-R-D-	Right Monitor for MX700 55 Dual Screen w/Dual Camera	There is currently no replacement product available for this product.	-	-
CTS-MX700-MON-R-D=	Spare Right Monitor for MX700 55 Dual Screen w/Dual Camera	There is currently no replacement product available for this product.	-	-
CTS-MX700-MON-R-S-	Right Monitor for MX700 55 Dual Screen w/ Single Camera	There is currently no replacement product available for this product.	-	-
CTS-MX700-MON-R-S=	Spare Right Monitor for MX700 55 Dual Screen w/ 1 cam	There is currently no replacement product available for this product.	-	-
CTS-MX700-MON-SCV-	Sidecover for MX700 Dual screen (left and right included)	There is currently no replacement product available for this product.	-	-
CTS-MX700-MON-SCV=	Sidecover for MX700 Dual screen (left and right included)	There is currently no replacement product available for this product.	-	-
CTS-MX700-MONLD++=	Spare Left Monitor MX700 55 Dual Screen w/Dual Cam TAA Comp	There is currently no replacement product available for this product.	-	-
CTS-MX700-MONLS++=	Spare Left Monitor for MX700 55 Dual Screen w/ 1 cam - TAA	There is currently no replacement product available for this product.	-	-
CTS-MX700-MONRD++=	Spare Right Monitor MX700 55 Dual Screen w/Dual Cam TAA Comp	There is currently no replacement product available for this product.	-	-
CTS-MX700-MONRS++=	Spare Right Monitor for MX700 55 Dual Screen w/ 1 cam TAA	There is currently no replacement product available for this product.	-	-
CTS-MX700-S-CAMCV-	Single cam top rear cover, Center Top profile and....	There is currently no replacement product available for this product.	-	-
CTS-MX700-S-CAMCV=	Single cam top rear cover, Center Top profile and....	There is currently no replacement product available for this product.	-	-
CTS-MX700800-CFBB-	Center Frame Bottom Bracket MX700 and MX800	There is currently no replacement product available for this product.	-	-
CTS-MX700800-CFBB=	Center Frame Bottom Bracket MX700 and MX800	There is currently no replacement product available for this product.	-	-
CTS-MX700D-1CAM-K9	Cisco MX700, Dual 55, Single Cam	CS-ROOM55D-K9	Cisco Webex Room 55D, Dual 55" Screens	Out of Stock, please purchase replacement product
CTS-MX700D-2CAM-K9	Cisco MX700, Dual 55, Dual Cam	CS-ROOM55D-K9	Cisco Webex Room 55D, Dual 55" Screens	-
CTS-MX800-D-CAMCV-	Dual cam top rear cover, Center Top profile and....	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
CTS-MX800-D-CAMCV=	Dual cam top rear cover, Center Top profile and.....	There is currently no replacement product available for this product.	-	-
CTS-MX800-D-FSK	Cisco MX800 Dual Screen Floor Stand Kit	There is currently no replacement product available for this product.	-	-
CTS-MX800-D-FSK=	Cisco MX800 Dual Screen Floor Stand Kit	There is currently no replacement product available for this product.	-	-
CTS-MX800-D-LGR-	MX800 Dual Lower Grill	There is currently no replacement product available for this product.	-	-
CTS-MX800-D-LGR=	MX800 Dual Lower Grill	There is currently no replacement product available for this product.	-	-
CTS-MX800-D-WMK	Cisco MX800 Dual Screen Wall Mount Kit - hangs on wall	There is currently no replacement product available for this product.	-	-
CTS-MX800-D-WMK=	Cisco MX800 Dual Screen Wall Mount Kit - hangs on wall	There is currently no replacement product available for this product.	-	-
CTS-MX800-DDC-TGR-	MX800 Dual - Dual Camera Top Grill	There is currently no replacement product available for this product.	-	-
CTS-MX800-DDC-TGR=	MX800 Dual - Dual Camera Top Grill	There is currently no replacement product available for this product.	-	-
CTS-MX800-DWM-LGR-	MX800 Dual Screen Wallmount Lower Grill	There is currently no replacement product available for this product.	-	-
CTS-MX800-DWM-LGR=	MX800 Dual Screen Wallmount Lower Grill	There is currently no replacement product available for this product.	-	-
CTS-MX800-MON-L-D-	Left Monitor for MX800 70 Dual Screen w/Dual Camera	There is currently no replacement product available for this product.	-	-
CTS-MX800-MON-L-D=	Left Monitor for MX800 70 Dual Screen w/Dual Camera	There is currently no replacement product available for this product.	-	-
CTS-MX800-MON-R-D-	Right Monitor for MX800 70 Dual Screen w/Dual Camera	There is currently no replacement product available for this product.	-	-
CTS-MX800-MON-R-D=	Right Monitor for MX800 70 Dual Screen w/Dual Camera	There is currently no replacement product available for this product.	-	-
CTS-MX800-MON-S-D-	Monitor for MX800 70	There is currently no replacement product available for this product.	-	-
CTS-MX800-MON-S-D=	Spare Monitor for MX800 70 Single Screen w/ Dual Camera	There is currently no replacement product available for this product.	-	-
CTS-MX800-MON-S-S-	Monitor for MX800 70 Single Screen w/Single Cam	There is currently no replacement product available for this product.	-	-
CTS-MX800-MON-S-S=	Spare Monitor for MX800 70 Single Screen, 1 cam	There is currently no replacement product available for this product.	-	-
CTS-MX800-MON-SCV-	Sidecover for MX800 (left and right included)	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
CTS-MX800-MON-SCV=	Sidecover for MX800 Dual screen (left and right included)	There is currently no replacement product available for this product.	-	-
CTS-MX800-MONLD++=	Left Monitor for MX800 70 Dual Screen w/Dual Cam TAA Comp	There is currently no replacement product available for this product.	-	-
CTS-MX800-MONRD++=	Right Monitor MX800 70 Dual Screen w/Dual Cam TAA Comp	There is currently no replacement product available for this product.	-	-
CTS-MX800-MONSD++=	Spare Monitor MX800 70 Single Screen w/ Dual Cam TAA Comp	There is currently no replacement product available for this product.	-	-
CTS-MX800-MONSS++=	Spare Monitor for MX800 70 Single Screen, 1 cam TAA Comp	There is currently no replacement product available for this product.	-	-
CTS-MX800-S-FSK	CTS-MX800-S-FSK Cisco MX800 Single Screen Floor stand kit	There is currently no replacement product available for this product.	-	-
CTS-MX800-S-FSK=	Cisco MX800 Single Screen Floor stand kit	There is currently no replacement product available for this product.	-	-
CTS-MX800-S-LGR-	MX800 Single Floorstand Lower Grill	There is currently no replacement product available for this product.	-	-
CTS-MX800-S-LGR=	MX800 Single Floorstand Lower Grill	There is currently no replacement product available for this product.	-	-
CTS-MX800-S-WMK	CTS-MX800-S-WMK Cisco MX800 Single Screen Wallmount kit	There is currently no replacement product available for this product.	-	-
CTS-MX800-S-WMK=	Cisco MX800 Single Screen Wallmount kit	There is currently no replacement product available for this product.	-	-
CTS-MX800-SDC-TGR-	MX800 Single - Dual Camera Top Grill	There is currently no replacement product available for this product.	-	-
CTS-MX800-SSC-TGR-	MX800 Single - Single Camera Top Grill	There is currently no replacement product available for this product.	-	-
CTS-MX800-SSC-TGR=	MX800 Single Single Camera Top Grill	There is currently no replacement product available for this product.	-	-
CTS-MX800-SWM-LGR-	MX800 Single Wallmount Lower Grill	There is currently no replacement product available for this product.	-	-
CTS-MX800-SWM-LGR=	MX800 Single Wallmount Lower Grill	There is currently no replacement product available for this product.	-	-
CTS-MX800D-2CAM-K9	Cisco MX800, Dual 70	CS-ROOM70DG2-K9	Cisco Webex Room 70 G2 Dual with Codec Pro and Touch10	-
CTS-MX800S-1CAM-K9	Cisco MX800, Single 70	CS-ROOM70SG2-K9	Cisco Webex Room 70 Single G2 with Codec Pro and Touch10	Out of Stock, please purchase replacement product.
CTS-MX800S-2CAM-K9	Cisco MX800, Single 70, Dual Camera	CS-ROOM70SG2-K9	Cisco Webex Room 70 Single G2 with Codec Pro and Touch10	-
CTS-MXCAM-D	^Dual Camera with speaker tracking option for MX700/MX800	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
CTS-MXCAM-D-	Dual Camera with speaker tracking option for MX700/MX800	There is currently no replacement product available for this product.	-	-
CTS-MXCAM-D=	Dual Camera with speaker tracking option for MX700/MX800	There is currently no replacement product available for this product.	-	-
CTS-MXCAM-S	^Single Camera option for MX700/MX800	There is currently no replacement product available for this product.	-	-
CTS-MXCAM-S-	Single Camera option for MX700/MX800	There is currently no replacement product available for this product.	-	-
CTS-MXCAM-S=	Single Camera option for MX700/MX800 Spare	There is currently no replacement product available for this product.	-	-
CTS-MXCODEC	Codec for MX700/MX800	There is currently no replacement product available for this product.	-	-
CTS-MXCODEC-	Codec for MX700/MX800	There is currently no replacement product available for this product.	-	-
CTS-MXCODEC=	Codec for MX700/MX800	There is currently no replacement product available for this product.	-	-
DOC-MX700-DDC-FSK	Installation sheet for MX700 dual camera, floor stand kit	There is currently no replacement product available for this product.	-	-
DOC-MX700-DDC-WMK	Installation sheet for MX700 dual camera, wall mount kit	There is currently no replacement product available for this product.	-	-
DOC-MX700-DSC-FSK	Installation sheet for MX700 single camera, floor stand kit	There is currently no replacement product available for this product.	-	-
DOC-MX700-DSC-WMK	Installation sheet for MX700 single camera, wall mount kit	There is currently no replacement product available for this product.	-	-
DOC-MX800-DDC-FSK	Installation sheet for MX800 dual camera, floor stand kit	There is currently no replacement product available for this product.	-	-
DOC-MX800-DDC-WMK	Installation sheet for MX800 dual camera, wall mount kit	There is currently no replacement product available for this product.	-	-
PWR-CAB-CHN-0.6M	Internal C13-C14 Power Cord for China, IEC60320, 3x18 AWG	There is currently no replacement product available for this product.	-	-
PWR-CAB-CHN-0.6M-	^Internal C13-C14 Power Cord for China, IEC60320, 3x18 AWG	There is currently no replacement product available for this product.	-	-
PWR-CAB-CHN-0.6M=	Internal C13-C14 Power Cord for China, IEC60320, 3x18 AWG	There is currently no replacement product available for this product.	-	-
PWR-CAB-CHN-1.4M	Internal C13-C14 Power Cord for China, IEC60320, 3x18 AWG	There is currently no replacement product available for this product.	-	-
PWR-CAB-CHN-1.4M=	Internal C13-C14 Power Cord for China, IEC60320, 3x18 AWG,	There is currently no replacement product available for this product.	-	-
PWR-CAB-CHN-1.85M	Internal C13-C14 Power Cord for China, IEC60320, 3x18 AWG,	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
PWR-CAB-CHN-1.85M-	^Internal C13-C14 Power Cord for China, IEC60320, 3x18 AWG,	There is currently no replacement product available for this product.	-	-
PWR-CAB-CHN-1.85M=	Internal C13-C14 Power Cord for China, IEC60320, 3x18 AWG,	There is currently no replacement product available for this product.	-	-
PWR-CAB-INT-0.6M	Internal C13-C14 Power Cord NOT APPROVED for China, 110/22	There is currently no replacement product available for this product.	-	-
PWR-CAB-INT-0.6M-	^Internal C13-C14 Power Cord NOT APPROVED for China, 110/22	There is currently no replacement product available for this product.	-	-
PWR-CAB-INT-0.6M=	Internal C13-C14 Power Cord NOT APPROVED for China, 110/22	There is currently no replacement product available for this product.	-	-
PWR-CAB-INT-1.4M	Internal C13-C14 Power Cord NOT APPROVED for China,	There is currently no replacement product available for this product.	-	-
PWR-CAB-INT-1.4M=	Internal C13-C14 Power Cord NOT APPROVED for China	There is currently no replacement product available for this product.	-	-
PWR-CAB-INT-1.85M	Internal C13-C14 Power Cord NOT APPROVED for China, IEC603	There is currently no replacement product available for this product.	-	-
PWR-CAB-INT-1.85M-	^Internal C13-C14 Power Cord NOT APPROVED for China, IEC603	There is currently no replacement product available for this product.	-	-
PWR-CAB-INT-1.85M=	Internal C13-C14 Power Cord NOT APPROVED for China, IEC603	There is currently no replacement product available for this product.	-	-

Product Migration Options

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at:

https://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco Telepresence MX700D, MX800S and MX800D through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <https://www.cisco.com/go/eos>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco End-of-Life Policy, go to:

https://www.cisco.com/en/US/products/products_end-of-life_policy.html.

For more information about the Cisco Product Warranties, go to:

https://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to:

<https://www.cisco.com/cisco/support/notifications.html>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)